Approved For Release 2001/08/13 : CIA-RDP78T05439A000500340010-2

ILLEGIB



Approved For Release 2001/08/13 : CIA-RDP78T05439A000500340010-2

~~CONFIDENTIAL~~

10507

CIA IMAGERY ANALYSIS DIVISION

NAME	COUNTRY	COORDINATES
Da Ben Highway Bridge Bridge No. 16 on NE 48-7	North Vietnam	18 25N - 105 48E WF 851362

25X1D

REFERENCES

PHOTO [redacted]

MAP AMS L509 NE 48-7

BRIEF NO: PIB - 65006

LOCATION: 0.2 nm N.E. Da Ben on Route 1

DESCRIPTION:

LENGTH	250'	MATERIAL	Steel and Concrete
WIDTH	12'	NO. OF SPANS	5
TYPE	Deck and Half-through Truss	LENGTH OF EACH SPAN	1-125, 3-35,1-20'

STATUS: Heavily damaged, 1 span dropped, approach interdicted

COMPENSATIVE ACTION: None



Declass Review by NIMA/DOD

~~CONFIDENTIAL~~